



Supports are separated from the part. Substantially large pitting is seen in the part wherever the supports were. You can see chunks of material pulled from the part at the end of the detached supports.



Virtually all supports on one side of the part were detached with chunks of material pulled from the part. This was observed during the print, which I subsequently abandoned and removed from the printer.


An example where a large amount of material was pulled out of the part by the support.



More examples...



More examples...



Large crack in the part
was discovered while the
printing was in process.

