

Onefinity Woodworker CNC Packing List

The Onefinity Woodworker CNC will arrive in three boxes.

Box #1: 48" x 13" x 9.5" / 45 lb (122cm X 33cm x 24.1cm / 20.4kG)

- X-Rail (3 bars if stiffy included. Box weight incl. stiffy option)
- Empty box used for filler/packing, may include any extra ordered accessories.

Box #2: 48" x 13" x 9.5" / 43.8 lb (122cm X 33cm x 24.1cm / 19.9kG)

- Y-Rail (Both Y rails interchangeable)
- Z-Axis Lift Mount

Box #3: 48" x 13" x 9.5" / 47.7 lb (122cm X 33cm x 24.1cm / 21.6kG)

- Y-Rail (Both Y rails interchangeable)
- Controller Unit
- Small box containing:
 - Touchscreen display monitor
 - Touchscreen display mounting arm
 - Controller AC Power Cord (Cord length = 67" not including ends)
 - Touchscreen Power Supply (Wire Length = 47")
 - Touchscreen USB cable (Length = 38")
 - Touchscreen HDMI cable (Length = 40")
 - M0 to X AXIS cable, Length = 43" (including connector ends)
 - M1 to Y AXIS cable, Length = 67" (including connector ends)
 - M2 to Y AXIS cable, Length = 26" (including connector ends)
 - M3 to Z AXIS cable, Length = 43" (including connector ends)
 - Hardware Bag, including:
 - (16) Wood Screws for mounting rails to table
 - (8) M6x22 Socket Head Cap screws for mounting X gantry to Y rails
 - (4) M5x70 Screws for mounting Touchscreen display mount
 - (4) M5 Nylon Lock Washer screws for securing M4x70 screws
 - (4) M5x10 Screws for mounting Z-Slider to X Gantry
- Box #3 may also include any additional purchased accessories such as router bits, dust boot, breakout adapter, spare cables, joystick, etc. Box #1 includes an additional box which may be used to ship accessories.